

Seite 1 von 1 : Artikel 1 - 3 von 3

<a href="#">ArtikelNr.</a> [1]	<a href="#">Artikel-Bezeichnung</a> [2]	Preis incl.
<a href="#">C 190/2</a> [3]	<a href="#">Carburater reapair-kit for Caravelle 1131 - SOLEX 32 PDIST - DITA</a> [3]	38,00 €
<a href="#">R 1572</a> [4]	<a href="#">Fuel filter with non-return valve - 6 mm</a> [4]	11,50 €
<a href="#">R 443</a> [5]	<a href="#">Fuel sensor, second typ with one cable connection - 4 CV 1955 -&gt;/Dauphine/Floride/Caravelle-Cabrio - 6/12 Volt</a> [5]	58,00 €



[PDF Version](#) [6]

---

Source URL (retrieved on 2026-05-25 08:58):<https://schuetzenhofer.de/en/catalog/128>

## Links

[1] <https://schuetzenhofer.de/en/catalog/128?order=model&sort=desc> [2]

<https://schuetzenhofer.de/en/catalog/128?order=title&sort=asc> [3]

<https://schuetzenhofer.de/en/content/carburater-reapair-kit-caravelle-1131-solex-32-pdist-dita> [4]

<https://schuetzenhofer.de/en/content/fuel-filter-non-return-valve-6-mm> [5] <https://schuetzenhofer.de/en/content/fuel-sensor-second-typ-one-cable-connection-4-cv-1955-dauphinefloridecaravelle-cabrio-612> [6]

<https://schuetzenhofer.de/en/printpdf/catalog/128>